















Strain Gauge - Tri-Axial

| GAGE PATTERN <small>Actual size shown. Enlarged when necessary for definition.</small> | | | | GAGE DESIGNATION <small>Insert desired S-T-C number in spaces marked XX. (9, 11, 16, 23, 27) ppm</small> | RES.IN OHMS | LEAD WIRES OPTIONS AVAILABLE |
|---|-----------------------|---------------------------|--------------------------|--|------------------------|---|
| Unit: millimeter | | | | | | |
| TS2-120 <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  3X </div> </div> | | | | Matrix Length: 5.56 Matrix Width: 5.56 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TS2-120-PC-XX | 120 | E,L,LE,PXX |
| 2.00 | 1.14 | 3.96 | 3.96 | | | |
| TS2-350 <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  3X </div> </div> | | | | Matrix Length: 5.56 Matrix Width: 5.56 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TS2-350-PC-XX | 350 | E,L,LE,PXX |
| 2.00 | 1.14 | 3.96 | 3.96 | | | |
| TS3-120 <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  2X </div> </div> | | | | Matrix Length: 7.13 Matrix Width: 7.13 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TS3-120-PC-XX | 120 | E,L,LE,PXX |
| 3.00 | 1.70 | 5.61 | 5.61 | | | |
| TS3-350 <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  2X </div> </div> | | | | Matrix Length: 7.13 Matrix Width: 7.13 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TS3-350-PC-XX | 350 | E,L,LE,PXX |
| 3.00 | 1.70 | 5.61 | 5.61 | | | |

Strain Gauge - Tri-Axial

| GAGE PATTERN <small>Actual size shown. Enlarged when necessary for definition.</small> | | | | GAGE DESIGNATION Insert desired S-T-C number in spaces marked XX. (0, 5, 9, 11, 17, 23) ppm | RES.IN OHMS | ENCAPSULATION and LEAD WIRES OPTIONS AVAILABLE |
|---|-----------------------|---------------------------|--------------------------|--|------------------------|---|
| Unit: millimeter | | | | | | |
| TR5-120I <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  1.5X </div> </div> | | | | Matrix Length: 14.00 Matrix Width: 14.00 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TR5-120I-PC-XX | 120 | E,L,LE,PXX |
| 4.25 | 3.19 | 11.83 | 11.83 | | | |
| TS7-120 <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  1.5X </div> </div> | | | | Matrix Length: 11.39 Matrix Width: 11.39 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TS7-120-PC-XX | 120 | E,L,LE,PXX |
| 6.50 | 3.13 | 9.50 | 9.50 | | | |
| TS7-350 <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  1X </div> <div style="text-align: center;">  1.5X </div> </div> | | | | Matrix Length: 11.39 Matrix Width: 11.39 | | |
| GAGE LENGTH | GRID WIDTH | OVERALL LENGTH | OVERALL WIDTH | TS7-350-PC-XX | 350 | E,L,LE,PXX |
| 6.50 | 3.13 | 9.50 | 9.50 | | | |